

Model	Drawing	L	T	W	$\theta$	C/R	E	F
cermet tips for hand saw								
4.3*1.7		4.3	1.7	1.8~2.2	15°	C0.5	1.0	0.3
4.5*1.8		4.5	1.8	1.8~2.2	10°	C0.5	0.5	0.2
4.5*1.8-1		4.5	1.8	1.8~2.2	7.7°	R0.5	1.0	0.38
4.5*1.8-2		4.5	1.8	1.8~2.2	15°	R0.5	1.0	0.38
5.0*1.5		5.0	1.5	2.0~3.4	10°	R0.5	2.0	0.5
5.0*1.5-1		5.0	1.5	2.0~3.4	25°	C0.41	1.0	0.3
5.0*2.0		5.0	2.0	2.0~3.4	15°	R0.5	1.5	0.4
6.0*2.0		6.0	2.0	2.2~4.5	15°	C0.5	1.0	0.5
6.0*2.0-1		6.0	2.0	2.2~4.5	15°	C0.5	-	-
6.0*2.0-2		6.0	2.0	2.2~4.5	15°	R0.5	1.5	0.5
6.5*2.5		6.5	2.5	2.2~4.5	15°	C0.5	-	-