

Model	Drawing	L	T	W	$\theta$	C/R	E	F
cermet tips for cold saw								
3.3*2.0		3.3	2.0	2.2~2.9	10°	R0.7	0.6	1.3
3.6*2.0		3.6	2.0	1.9~2.3	12°	R0.5	0.65	0.6
4.2*2.3		4.2	2.3	2.2~3.5	12°	R0.5	0.76	1.8
4.5*2.6		4.5	2.6	2.2~3.5	10°	C0.5	-	-
4.5*2.6-1		4.5	2.6	2.2~3.5	10°	C0.5	-	-
4.5*2.6-3		4.5	2.6	2.2~3.5	10°	R0.7	0.88	1.9
4.8*2.5		4.8	2.5	3.8~4.0	8°	R0.5	-	-